



# Product Safety Recall

Models Covered	Serial Range
V8 200–300 and V6 175–225 FourStroke, Pro XS®, SeaPro™, and Verado® Models	V8 2B529482 – 3B430915 V6 2B529482 – 3B421321
V8 250R, V8 300R and 300R HD Models	1E080500 – 1E091195 2B529482 – 3B430915



## Do you own this product?

Affected marine outboard engines:

- V8 200–300 HP and V6 175–225 HP FourStroke, Pro XS®, SeaPro™ and Verado® Model outboard engines

- V8 250R, V8 300R and 300R HD Model outboard engines

Dates sold: 1 September 2018 – 25 October 2023



**Why the product is recalled:** The air vents of the affected engine cover may allow for fingers to be placed through the air vent gaps.

**Hazard:** There is a risk of serious injury including amputation or lacerations to fingers if placed through the air vents. Injuries have occurred because of this hazard.



Consumers with affected products should contact their Mercury dealer to arrange for a bezel assembly to be installed over the air vents.



For more information contact Marine Power International on 03 9791 5822 or email [merc.info@mercmarine.com](mailto:merc.info@mercmarine.com)



Purchased from: See traders list on the [productsafety.gov.au](http://productsafety.gov.au) website

PRA2023/19969

See [productsafety.gov.au](http://productsafety.gov.au) for Australian product recall information